

Ferris State University  
Manufacturing Engineering Technology

# Project X

2008

Frank Kruger  
Preston Ostrander  
Brian Wyns  
Nicholas Yax

- I Index
- II Project Overview
- III Finished Part Print
- IV Flow Chart
- V Process Routing
- VI Tolerance Charts
- VII Operation Documentation
  - a Operation Sheets
  - b Process Sheets
  - c Tool Layout Sheets
- VIII Appendix
  - a Standard Operating Procedures

## Project–X 2008

Vise Stop


Part Number: PX – 2008

Launch: February 25, 2008

Complete: March 7, 2008

### Overview

1. Determine the most economical method for manufacturing the simple part, in small lots.
2. Develop a simple routing that shows order of operations and equipment used at each operation.
3. Develop process dimensions and tolerances that are consistent with anticipated work holding datums.
4. Design work holding systems for the machining of a simple piece part using standard work holding components.
5. Assure work holding systems are consistent with anticipated process tolerance stacks and will not hinder achieving process dimensions and tolerances.
6. Completely document a manufacturing operation using Operation Sheets, Operation Setup Sheets, Tooling Layouts, and Standard Operating Procedures where applicable.
7. Run production following your process plan to produce the required number of parts.



Material: 1018 C.R.S.


.X =  $\pm .1$   
.XX =  $\pm .01$   
.XXX =  $\pm .001$

# Process Flow Chart

## Job Information:

Customer: Ferris State University

Job: Vise Stop



## Sign-Off / Approval

Documented By/ Date:

Approved By/ Date:

## PROCESS ROUTING

**PART #-** PX-2008  
**PART NAME-** VISE STOP  
**ENGINEERS-** FRANK KRUGER  
PRESTON OSTRANDER  
NICK YAX  
BRIAN WYNS

**OP 10-** MATERIAL RECEIVED, INSPECT AND DETERMINE CONFORMANCE

**OP 20-** SAW RAW STOCK INTO SLUGS FOR MACHINING

**OP 30-** MANUALLY DEBURR ALL SHARP EDGES AND CLEAN

**OP 40-** CLEAN UP ONE END OF PART TO ESTABLISH DATUM

**OP 50-** MANUALLY DEBURR SHARP EDGES AND CLEAN

**OP 60-** SQUARE REMAINING END TO 1.00"  $\pm .005$

**OP 70-** MANUALLY DEBURR SHARP EDGES AND CLEAN

**OP 80-** CENTERDRILL, DRILL, AND RIGID TAP HOLE

**OP 90-** MANUALLY REMOVE CHIPS AND COOLANT FROM HOLE, CLEAN

**OP 100-** MILL SLOT AND STEP FEATURES IN PART

**OP 110-** MANUALLY DEBURR SHARP EDGES AND CLEAN

**OP120-** FINAL INSPECTION


**OP 130-** SHIPPING

Part Number: PX-2008

Part Name: Vise Stop

Engineer's Name: KRUGER, WYNS, OSTRANDER, YAX

Notes:



line no	Op no	Stock Adders	Machine to		a	b	c	d	e	f	g	h	i	j	k	l	Balance Dimensions		Line Equation	Stock Removal Allowances	
			Mean	+/-tol													Mean	+/-tol		Mean	+/-tol
1			1.249	.001																	
2	80	-.01	.995	.005																	
3																					
4	80	.01	.255	.005																	
5																					
6																					
7																					
8																					
9	80		1.005	.003																	
10																					
11	80		.760	.005																	
12																					
13																					
14																					
15																					
16																					
17																					
18																					
19																					
20																					
21																					
22																					
23																					
24																					
25																					
26																					
27																					
28																					
29																					
30																					

PF	Description	Dimensions		Product Drawing Balance Dimensions										Resultant Data		Tolerance Path	
31		1.249	0.010											1.249	.001	1	
32		0.760	0.005											.760	.005	11	
33		0.245	0.010											.245	.004	10, 9, 1	
34																	
35																	
36																	


a | b | c | d | e | f | g | h | i | j | k | l |

Part Number: PX-2008

Part Name: Vise Stop

Engineer's Name: KRUGER, WYNS, OSTRANDER, YAX

Notes:



line no	Op no	Stock Adders	Machine to		a  b  c	d  e  f  g	h  i  j  k	l	Balance Dimensions		Line Equation	Stock Removal Allowances		
			Mean	+/-tol					Mean	+/-tol		Mean	+/-tol	
1	50	.02, .02	1.040	0.010		← 1			SAW	—			→	
2														
3	60	.02	1.020	0.005		← 3					1 - 3	0.020	0.015	
4														
5														
6	60		1.000	0.005		6 →					3 - 6	0.020	0.010	
7														
8														
9	70		0.500	0.0035		9 →			SOLID	—			→	
10														
11														
12														
13														
14														
15														
16														
17														
18														
19														
20														
21														
22														
23														
24														
25														
26														
27														
28														
29														
30														
PF	Description		Dimensions		Product Drawing Balance Dimensions					Resultant Data		Tolerance Path		
31			1.000	0.010		● 31		●	1.000	0.010	6			
32			0.500	0.0035		● 32	●		0.500	0.005	9			
33														
34														
35														
36														

a | b | c | d | e | f | g | h | i | j | k | l |




Part Number: PX-2008

Part Name: Vise Stop

Engineer's Name: KRUGER, WYNS, OSTRANDER, YAX

Notes:



line no	Op no	Stock Adders	Machine to												Balance Dimensions		Line Equation	Stock Removal Allowances	
			Mean	+/-tol	a	b	c	d	e	f	g	h	i	j	k	l		Mean	+/-tol
1			0.499	0.001													As Purchased		
2																			
3	70		0.200	0.0035													Solid		
4																			
5	80		0.230	0.005													Solid		
6																			
7	80		0.380	0.005													Solid		
8																	0.150	0.010	7 - 5
9																			
10																			
11																			
12																			
13																			
14																			
15																			
16																			
17																			
18																			
19																			
20																			
21																			
22																			
23																			
24																			
25																			
26																			
27																			
28																			
29																			
30																			

PF	Description	Dimensions		Product Drawing Balance Dimensions										Resultant Data		Tolerance Path	
31		0.380	0.010											0.380	0.005	4	
32		0.150	0.010											0.150	0.010	8, 7, 5	
33		0.499	0.001											0.499	0.001	1	
34		0.200	0.0035											0.200	0.010	3	
35																	
36																	

a | b | c | d | e | f | g | h | i | j | k | l |

<b>Op 20</b>	<b>Operation Set Up Sheet</b>					
<b>Op Description:</b>	SAW SLUGS					<b>Date:</b> 3/6/08
<b>Part Name:</b>	WISE STOP	<b>Part No:</b>	PX-2008			<b>Material:</b> 1018 CRS
<b>Department:</b>	FSU SWN 122	<b>Machine:</b>	WELLS BANDSAW	<b>Engineers:</b>	KRUGER, WYNS OSTRANDER, YAX	<b>Revision:</b> N/A

TOOLPATH IS Z- AXIS

BLADE DIRECTION Z-







<b>Tool Path</b>	<b>Locator</b>	<b>Clamp</b>	<b>Target Datum</b>
------------------	----------------	--------------	---------------------


  

<b>Set Up Notes</b>
WISE SQUARENESS MUST BE CHECKED BEFORE CUTTING
SET STOP TO CUT SLUGS 1.040 +/- .025
STOP MUST REMAIN FREE OF CHIPS TO ENSURE REPEATABILITY
CHECK EVERY 5TH PART TO ENSURE CONSISTENCY
BLADE SPEED SET TO 150 SFPM
BLADE FEED SET TO 5 ON FLOW CONTROL

Op 30	Operation Sheet						
Op Description:	MANUAL DEBURR AND CLEAN				Date:	3/6/08	
Part Name:	WISE STOP	Part No:	PX-2008		Material:	1018 CRS	
Department:	FSU SWN 122	Machine:	N/A	Engineers:	KRUGER WYNS OSTRNADER YAX	Revision:	N/A
<div><div></div><div>(1.04")</div><div>(1.25")</div></div>							
<div><div>→ Tool Path</div><div>▷ Locator</div><div>▶ Clamp</div><div>◐ Target Datum</div><div>&lt;Reference&gt;</div></div>							
Set Up Notes							
MANUALLY DEBURR ALL EDGES WITH FILE							
WIPE COOLANT, CHIPS AND SWARF OFF PART WITH SHOP RAG							

Op 40		Operation Sheet																				
Op Description:		SQUARE END				Date:	3/6/08															
Part Name:		WISE STOP	Part No:	PX-2008		Material:	1018 CRS															
Department:		FSU SWN 122	Machine:	HURCO VM-1	Engineers:	KRUGER WYNS OSTRANDER YAX	Revision:	N/A														
<div style="text-align: center;"><p>The diagram shows a rectangular workpiece with a width dimension of 1.020 indicated by a double-headed arrow below it. To the left of the rectangle is a circle labeled "TOOL". An upward-pointing arrow connects the tool circle to the bottom-left corner of the rectangle. Above the top edge of the rectangle is a small inverted triangle symbol. At the top-right corner of the rectangle, there is a circular target datum symbol (a circle divided into four quadrants) and a blue triangular locator symbol pointing towards the corner. The text "Vise Stop" is written to the right of the blue triangle.</p></div>																						
<div style="display: flex; justify-content: space-between; align-items: center;"><div> Tool Path</div><div> Locator</div><div> Clamp</div><div> Target Datum</div></div> <div><b>Reference Documentation</b><table><tr><td>PX-2008-40-SU</td><td>Setup Sheet</td><td></td></tr><tr><td>PX-2008-40-TL</td><td>Tool Layout</td><td></td></tr><tr><td> </td><td> </td><td> </td></tr><tr><td> </td><td> </td><td> </td></tr><tr><td> </td><td> </td><td> </td></tr></table></div>								PX-2008-40-SU	Setup Sheet		PX-2008-40-TL	Tool Layout										
PX-2008-40-SU	Setup Sheet																					
PX-2008-40-TL	Tool Layout																					

<b>Op 40</b>		<b>Setup Sheet</b>					
<b>Op Description:</b>		SQUARE END				<b>Date:</b>	3/6/08
<b>Part Name:</b>	WISE STOP	<b>Part No:</b>	PX-2008			<b>Material:</b>	1018 CRS
<b>Department:</b>	FSU SWN 122	<b>Machine:</b>	HURCO VM-1	<b>Engineers:</b>	KRUGER WYNS OSTRANDER YAX	<b>Revision:</b>	N/A
							
<div>  <b>Tool Path</b>  <b>Locator</b>  <b>Clamp</b>  <b>Target Datum</b>  <b>&lt;Reference&gt;</b> </div>							
<b>Set Up Notes</b>							
VISE SQUARENESS MUST BE CHECKED BEFORE CUTTING SET UP VISE STOP SO .125" ACCESSIBLE MATERIAL FOR ENDMILL SETUP MUST REMAIN FREE OF CHIPS TO ENSURE REPEATABILITY CHECK EVERY 5TH PART TO ENSURE CONSISTENCY							
<b>Operation Control Plan</b>							
<div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> <div></div> </div>							
<b>Operation Sequence</b>							
Operation Sequence				Tool			
Sequence	Element Description	RPM	Feed	Control	Qty	Description	
60.1	MILL END	2500	12 IPM	NC	1	1/2" CARBIDE UNCOATED 2-FLUTE ENDMILL	

Op 40		Tool Layout						
Op Description:		SQUARE END				Date:	3/6/08	
Part Name:		WISE STOP	Part No:	PX-2008		Material:	1018 CRS	
Department:		FSU SWN 122	Machine:	HURCO VM-1	Engineers:	KRUGER WYNS OSTRANDER YAX	Revision:	N/A
40.1		1/2" CARBIDE 2-FLUTED END MILL, UNCOATED						
								



<b>Op 60</b>		<b>Operation Sheet</b>			
<b>Op Description:</b>		SQUARE END & MACHINE TO SIZE			<b>Date:</b> 3/6/08
<b>Part Name:</b>	WISE STOP	<b>Part No:</b>	PX-2008		<b>Material:</b> 1018 CRS
<b>Department:</b>	FSU SWN 122	<b>Machine:</b>	HURCO VM-1	<b>Engineers:</b> KRUGER, WYNS, OSTRANDER YAX	<b>Revision:</b> N/A

The diagram shows a rectangular part with a circular tool labeled 'TOOL' to its left. An arrow points from the tool to the left side of the rectangle. Above the rectangle is a triangle pointing down. Below the rectangle is a triangle pointing up. To the right of the rectangle is a blue triangle pointing left, labeled 'Vise Stop'. A dimension line below the rectangle indicates a width of 1.000".

<b>Tool Path</b>	<b>Locator</b>	<b>Clamp</b>	<b>Target Datum</b>
<b>Reference Documentation</b>			
PX-2008-60-SU	Setup Sheet		
PX-2008-60-TL	Tool Layout		






Op 60		Setup Sheet						
Op Description:		SQUARE END & MACHINE TO SIZE				Date:	3/6/08	
Part Name:		WISE STOP	Part No:	PX-2008		Material:	1018 CRS	
Department:		FSU SWN 122	Machine:	HURCO VM-1	Engineers:	KRUGER, WYNS, OSTRANDER YAX	Revision:	N/A
								
<div>————→ Tool Path      ► Locator      ▷ Clamp      ◐ Target Datum      &lt;Reference&gt;</div>								
Set Up Notes								
WISE SQUARENESS MUST BE CHECKED BEFORE CUTTING								
SET UP WISE STOP SO .125" ACCESSIBLE MATERIAL FOR ENDMILL								
SETUP MUST REMAIN FREE OF CHIPS TO ENSURE REPEATABILITY								
CHECK EVERY 5TH PART TO ENSURE CONSISTENCY								
Operation Control Plan								
Operation Sequence								
Sequence	Element Description	RPM	Feed	Control	Qty	Description		
60.1	MILL END	2500	12 IPM	NC	1	1/2" CARBIDE UNCOATED 2-FLUTE ENDMILL		

[illegible]

Op 70	Operation Sheet						
Op Description:	MANUAL DEBURR AND CLEAN				Date:	3/6/08	
Part Name:	WISE STOP	Part No:	PX-2008		Material:	1018 CRS	
Department:	FSU SWN 122	Machine:	N/A	Engineers:	KRUGER WYNS OSTRNADER YAX	Revision:	N/A
<div><div></div><div>(1.00")</div><div>(1.25")</div></div>							
<div><div>→ Tool Path</div><div>▷ Locator</div><div>▶ Clamp</div><div>⊞ Target Datum</div><div>&lt;Reference&gt;</div></div>							
Set Up Notes							
MANUALLY DEBURR ALL SHARP EDGES WITH FILE							
WIPE COOLANT, CHIPS AND SWARF OFF PART WITH SHOP RAG							

<b>Op 80</b>		<b>Operation Setup Sheet</b>				
<b>Op Description:</b>		CENTER DRILL, DRILL, AND TAP			<b>Date:</b>	3/6/08
<b>Part Name:</b>	WISE STOP	<b>Part No:</b>	PX-2008		<b>Material:</b>	1018 CRS
<b>Department:</b>	FSU SWN 122	<b>Machine:</b>	HURCO VM1	<b>Engineers:</b>	KRUGER WYNS OSTRANDER YAX	<b>Revision:</b> N/A
<div style="text-align: center;"> </div>						
<div style="display: flex; justify-content: space-around; align-items: center;"> <span>→ Tool Path</span> <span>▷ Locator</span> <span>◁ Clamp</span> <span>⊙ Target Datum</span> <span>&lt;Reference&gt;</span> </div>						
<b>Set Up Notes</b>						
VISE SQUARENESS MUST BE CHECKED BEFORE CUTTING SET STOP TO INSURE PROPER HOLE LOCATION KEEP VISE CLEAN AND FREE OF CHIPS CHECK EVERY FIFTH PART TO ENSURE CONSISTENCY						
<b>Reference Documentation</b>						
PX-2008-80-TL Tool Layout						
<b>Operation Sequence</b>				<b>Tool</b>		
<b>Sequence</b>	<b>Element Description</b>	<b>RPM</b>	<b>Feed</b>	<b>Control</b>	<b>Qty</b>	<b>Description</b>
80.1	CENTER DRILLING	2000	4 ipm	NC	1	Center Drill
80.2	DRILLING	1500	4 ipm	NC	1	# 7 Drill
80.3	TAPPING	100	5 ipm	NC	1	.25-20-UNC RIGID TAP


Op 80		Tool Layout						
Op Description:		CENTER DRILL, DRILL AND TAP				Date:	3/6/08	
Part Name:		WISE STOP	Part No:	PX-2008		Material:	CRS	
Department:		FSU SWN 122	Machine:	HURCO VM1	Engineers:	KRUGER WYNES OSTRANDER YAX	Revision:	N/A
80.1		# 3 CENTER DRILL						
								
80.2		# 7 DRILL						
								
80.3		1/4-20-UNC OSG HI PRO TAP						
								








Op 100	Operation Sheet						
Op Description:	Mill Slot and Step					Date:	3/6/08
Part Name:	WISE STOP	Part No:	PX-2008			Material:	1018 CRS
Department:	FSU SWN 122	Machine:	HURCO VM-1	Engineers:	KRUGER WYNES OSTRANDER YAX	Revision:	N/A
<div><div>→ Tool Path</div><div>▶ Locator</div><div>▷ Clamp</div><div>⊙ Target Datum</div></div> <div>Reference Documentation</div> <div>PX-2008-100-SU Setup Sheet</div> <div>PX-2008-100-TL Tool Layout</div> <div></div> <div></div> <div></div> <div></div> <div></div>							

[illegible]



<b>Op 100</b>		<b>Tool Layout</b>							
<b>Op Description:</b>		MILL SLOT AND STEP				<b>Date:</b>	3/6/08		
<b>Part Name:</b>		VISE STOP		<b>Part No:</b>	PX-2008		<b>Material:</b>	1018 CRS	
<b>Department:</b>		FSU SWN 122		<b>Machine:</b>	HURCO VM1	<b>Engineers:</b>	KRUGER WYNS OSTRANDER YAX	<b>Revision:</b>	N/A
100.1		1/2 IN. UNCOATED END MILL							
									

Op 110	Operation Sheet						
Op Description:	MANUAL DEBURR AND CLEAN				Date:	3/6/08	
Part Name:	WISE STOP	Part No:	PX-2008		Material:	1018 CRS	
Department:	FSU SWN 122	Machine:	N/A	Engineers:	KRUGER WYNS OSTRNADER YAX	Revision:	N/A
<div></div>							
<div><div> Tool Path</div><div> Locator</div><div> Clamp</div><div> Target Datum</div><div>&lt;Reference&gt;</div></div>							
Set Up Notes							
MANUALLY DEBURR ALL SHARP EDGES WITH FILE							
WIPE COOLANT, CHIPS AND SWARF OFF PART WITH SHOP RAG							

## Indicating Vice


**Purpose:** To insure that vice is aligned to x-axis of vertical milling machine.

**Scope:** Applies to cnc and manual vertical milling machines and their vices.

**Equipment:** Test indicator, dead blow hammer, adjustable wrench, Indicol holder.

### Steps:

1. Place indicol around mill spindle.
2. Insert test indicator into indicol.
3. Loosen vice, with adjustable wrench.
4. Snug right nut of vice.
5. Move test indicator to back left jaw as shown.



6. Preload indicator  $\frac{1}{2}$  travel and Set to zero by moving mill table about y- axis.
7. Move test indicator to right side of jaw, while observing needle move.
8. Tap vice with dead blow hammer, until test indicator goes back towards zero.
9. Repeat steps 7 through 10 until Total Indicator Reading is within spec.
10. Tighten vice with adjustable wrench.
11. Repeat steps 7 through 9.
11. Process is complete when total indicator reading is zero.